

Monitoring Results for Water Supply Emergency Order

Quality of Untreated Water Entering Mianus Water Treatment Plant

ND = not detected

| Raw Water Quality Standards | 250 CU | 250 NTU | 20000/100ml | 1 ug/L | 1 ug/L | |
|-----------------------------|--------|---------|----------------|-------------|--------------------|--|
| Date | Color | Turb | Total Coliform | Microcystin | Cylindrospermopsin | |
| 12/1/2016 | 92 | 2.9 | weekly | No sample | No sample | |
| 12/2/2016 | 34 | 2.0 | weekly | No sample | No sample | |
| 12/3/2016 | 53 | 1.5 | weekly | No sample | No sample | |
| 12/4/2016 | 47 | 1.4 | weekly | No sample | No sample | |
| 12/5/2016 | 49 | 1.3 | 2760 | ND | ND | |
| 12/6/2016 | 42 | 1.3 | weekly | No sample | No sample | |
| 12/7/2016 | 38 | 1.3 | weekly | No sample | No sample | |
| 12/8/2016 | 40 | 1.3 | weekly | No sample | No sample | |
| 12/9/2016 | 42 | 1.2 | weekly | No sample | No sample | |
| 12/10/2016 | 40 | 1.3 | weekly | No sample | No sample | |
| 12/11/2016 | 35 | 1.3 | weekly | No sample | No sample | |
| 12/12/2016 | 33 | 1.3 | 1850 | ND | pending | |
| 12/13/2016 | 37 | 1.3 | weekly | No sample | No sample | |
| 12/14/2016 | 32 | 1.3 | weekly | No sample | No sample | |